



**License Plate Survey**  
**Friday - 10/5/07**

Northbound		
PM	FROM	TO
	LOCATION 1	LOCATION 2
	Cliff/Stockton	Capitola/Trestle
<b>Total Plates</b>	639	
<b>Total Matched Plates</b>		206
<b>% of Matched Plates</b>		32%

  

PM	FROM	TO
	LOCATION 1	LOCATION 3
	Cliff/Stockton	Monterey/Fanmar
<b>Total Plates</b>	639	
<b>Total Matched Plates</b>		378
<b>% of Matched Plates</b>		59%

  

PM	FROM	TO
	LOCATION 2	LOCATION 3
	Capitola/Trestle	Monterey/Fanmar
<b>Total Plates</b>	289	
<b>Total Matched Plates</b>		113
<b>% of Matched Plates</b>		39%

Note: The eastbound movement from Capitola/Trestle (Location 2) to Monterey/Fanmar (Location 3) identified in Table 3 of the traffic report has been renamed to a northbound movement in this exhibit.

Figure 7A