



**License Plate Survey**  
**Friday - 10/5/07**

Southbound		
PM	FROM	TO
	LOCATION 2	LOCATION 1
	Capitola/Trestle	Cliff/Stockton
<b>Total Plates</b>	289	
<b>Total Matched Plates</b>		107
<b>% of Matched Plates</b>		37%
PM	FROM	TO
	LOCATION 3	LOCATION 1
	Monterey/Fanmar	Cliff/Stockton
<b>Total Plates</b>	358	
<b>Total Matched Plates</b>		144
<b>% of Matched Plates</b>		40%
PM	FROM	TO
	LOCATION 3	LOCATION 2
	Monterey/Fanmar	Capitola/Trestle
<b>Total Plates</b>	358	
<b>Total Matched Plates</b>		79
<b>% of Matched Plates</b>		22%

Note: The westbound movement from Monterey/Fanmar (Location 3) to Capitola/Trestle (Location 2) identified in Table 3 of the traffic report has been renamed to a southbound movement in this exhibit.

Figure 7B